
N

Safe Home No Messin' When Processin'





The factory is a busy working area with moving machinery. Conditions are made more difficult when in heavy seas. Everyone on board has a responsibility for their own safety and the safety of others. If you see a hazard – report it!

- Guards must be in place when a conveyor or machinery is running.
- Never over-ride machinery safety interlocks.
- Always follow proper lockouttagout procedures during periods of repair and maintenance.
- Make sure your work area and path is clear from obstructions and trip hazards.
- Dress correctly for work and use the proper personal protective equipment (PPE).
- Practice safe manual handling and take care when lifting heavy items.
- Always maintain good seamanship and good housekeeping.
- Keep factory safety equipment in good working order – one day your life may depend on it!

Global service built around you

For more information, please visit www.nepia.com 🈏 😭 🖬 🖸

Copyright ${\small ©}$ 2019 The North of England P&I Association Limited

POSTER: 1

MEMBER OF